

☐ SECRET

Approved For Release 2006/12/01 : CIA-RDP78B04770A002500090019-7

☒ CONFIDENTIAL☐ UNCLASSIFIED

CONTRACT INSPECTION REPORT		CONTRACT NO.	TASK NO.		
TO: CONTRACT ADMINISTRATION & SETTLEMENT BRANCH/PD/OL		DATE <b>27 November 1967</b>	25X1		
		INSPECTION REPORT NO. (If final, so state) <b>5</b>			
		ESTIMATED COMPLETION DATE <b>30 January 1967</b>			
NAME OF CONTRACTOR <div style="border: 1px solid black; height: 20px; width: 500px;"></div>					
TYPE OF COMMODITY OR SERVICE <b>Prototype Development Wide Print Straightener</b>					
THE CONTRACTOR IS ON SCHEDULE <input type="checkbox"/> YES <b>NA</b> <input type="checkbox"/> NO		THE CONTRACTOR WILL PROBABLY REMAIN WITHIN ALLOCATED FUNDS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF ANSWER IS "NO" ADVISE RECOMMENDATION AND/OR ACTION OF SPONSORING OFFICE, ON REVERSE HEREOF. IF KNOWN, INDICATE MAGNITUDE OF ADDITIONAL FUNDS INVOLVED.			
PER CENT OF WORK COMPLETED - <b>100%</b>					
PER CENT OF FUNDS EXPENDED - <b>100%</b>					
HAS AN INTERIM REPORT, FINAL REPORT, PROTOTYPE, OR OTHER END ITEM BEEN RECEIVED FROM THE CONTRACTOR DURING THE PERIOD? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (If yes, give details on reverse side.)					
HAS GOVERNMENT-OWNED PROPERTY BEEN DELIVERED TO CONTRACTOR DURING THIS PERIOD? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (If yes, indicate items, quantity, and cost on reverse side.)					
INCENTIVES					
IS THIS AN INCENTIVE CONTRACT <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, CHECK TYPE <input type="checkbox"/> COST <input type="checkbox"/> AWARD FEE <input checked="" type="checkbox"/> PERFORMANCE <input type="checkbox"/> DELIVERY		NOTE: USE REVERSE SIDE FOR COMMENTS. FINAL REPORT MUST CONTAIN INCENTIVE EVALUATION.			
OVERALL PERFORMANCE OF CONTRACTOR					
1. <input type="checkbox"/> OUTSTANDING 4. <input type="checkbox"/> ABOVE AVERAGE 7. <input type="checkbox"/> UNSATISFACTORY					
2. <input type="checkbox"/> EXCELLENT 5. <input checked="" type="checkbox"/> AVERAGE					
3. <input type="checkbox"/> VERY GOOD 6. <input type="checkbox"/> MINIMUM ACCEPTABLE					
IF OVERALL PERFORMANCE OF CONTRACTOR IS UNSATISFACTORY OR MINIMUM ACCEPTABLE INDICATE REASONS ON REVERSE SIDE.					
RECOMMENDED ACTION					
<input checked="" type="checkbox"/> CONTINUE AS PROGRAMMED <input type="checkbox"/> WITHHOLD PAYMENT PENDING SATISFACTORY PERFORMANCE					
<input type="checkbox"/> TERMINATE <input type="checkbox"/> OTHER (Specify)					
IF TERMINATION IS RECOMMENDED OR IF THIS IS A FINAL REPORT PUT COMMENTS ON REVERSE IN NARRATIVE FORM ON CONTRACTOR'S PERFORMANCE AND CERTIFY THAT ALL DELIVERABLE ITEMS UNDER THE CONTRACT HAVE BEEN RECEIVED. THESE INCLUDE, WHERE APPLICABLE, THE FOLLOWING:					
ITEM	REC'D	DOES NOT APPLY	ITEM	REC'D	DOES NOT APPLY
PROTOTYPES			MANUALS		
DRAWINGS AND SPECIFICATIONS			FINAL REPORT		
PRODUCTION AND/OR OTHER END ITEMS			SPECIAL TOOLING		
			OTHER GOVERNMENT PROPERTY		
DATE OF LAST CONTACT WITH CONTRACTOR <b>late October 1967</b>					
SIGNATURE OF INSPECTOR <div style="border: 1px solid black; height: 20px; width: 150px;"></div>			DIVISION <b>TDS/DS</b>		
INSPECTOR'S EXTENSION <div style="border: 1px solid black; height: 20px; width: 60px;"></div>			SIGNATURE OF APPROVER <div style="border: 1px solid black; height: 20px; width: 180px;"></div>		

NARRATIVE REPORT

☒ INTERIM

☐ FINAL

The Equipment Performance Staff performed an acceptance test on the Wide Print Straightener, but I have not yet received the report on test and therefore cannot recommend acceptance at this time. However, I have been verbally informed that the equipment did not perform satisfactorily. I anticipate eventual acceptance of the equipment and then modifications in-house to meet our requirements since this appears the fastest and least expensive route at this time. The contractor while answering my past complaints concerning the equipment, did not answer them promptly. Shortly after delivery, it became obvious that the equipment had several shortcomings. I suggested that they take the machine back and put it in good operating order. However, they preferred to make a series of minor modifications on the equipment at NPIC. None of the modifications solved the problem but merely transferred the deficiencies to another part of the machine.

☐ UNCLASSIFIED

☒ CONFIDENTIAL

☐ SECRET